

The diagram illustrates a road cross-section with a 2% slope. At the top, a horizontal line with arrows at both ends is labeled "3,0-4,0" and "CHODNÍK". Below this, a person is shown walking on the path. The road surface is marked with a "2%" slope indicator. The road is divided into three sections: "OHUMUSOVÁNÍ" (mulching) on the left, "DLAŽBA" (paving) in the center, and "OHUMUSOVÁNÍ" (mulching) on the right. The road is flanked by "ZELEN" (greenery) on both sides. The road is marked with "DLE SIT" (according to the standard) and "±0" (zero elevation) at the center.

<p><b>PPU</b> spol. s r.o.</p> <p>INŽENÝRSKÝ ATELIER PORADENSTVÍ - PROJEKCE - URBANISMUS</p> <p>VYŽLOVSKÁ 2243 / 36, 100 00 PRAHA 10</p>	<p>DOPRAVA, KOMUNIKACE, TERÉNNÍ ÚPRAVY INŽENÝRSKÉ SÍTĚ, TECHNICKÁ INFRASTRUKTURA ŽIVOTNÍ PROSTŘEDÍ, HLUK, EXHALACE POČÍTAČOVÉ ZPRACOVÁNÍ, PLOTROVÁNÍ</p>	<p>ZÁPIS V OBCHODNÍM REJSTŘÍKU U MĚSTSKÉHO SOUDU V PRAZE, ODDÍL C, Č.VLOŽKY 20939, IČ 49613481</p>
--	--	--

ZÁPIS V OBCHODNÍM REJSTŘÍKU U MĚSTSKÉHO SOUDU  
V PRAZE, ODDÍL C, Č.VLOŽKY 20939, IČ 49613481

DATUM: 06/2024

**PPU** spol. s r.o.  
INŽENÝRSKÝ ATELIER  
PORADENSTVÍ - PROJEKCE - URBANISMUS  
VYŽLOVSKÁ 2243 / 36, 100 00 PRAHA 10