

II/106, most ev.č. 106 – 001 Štěchovice - PD

Bilance zemních prací

SO	výkop [m ³]	násyp z výkopu [m ³]	násyp nový mat. [m ³]	AZ [m ³]	ornice [m ³]		
					sejmutí	ohumusování	
						svah	rovina
201	1 156	126	937	93	0	0	0
celkem	1 156	126	937	93	0	0	0
nedostatek:	1 030				0		